# TRUE NORTH

#### ◆ GEOTECHNICAL ◆

### **TECHNICAL MEMORANDUM**

Date: June 28, 2023

From: David Rankin, CEG, Principal Engineering Geologist

Tima Carlson, RG, Project Geologist

To: Katrina Dawson, Cottrell CPO

**RE:** Portland Water Bureau Water Filtration Project

**Initial Cursory Review** 

**True North Project: 23-0108** 



**EXPIRES 6/1/24** 

True North was contracted by Cottrell CPO to provide Initial/Cursory Geologic and Geotechnical Review for the proposed Portland Water Bureau (PWB) Water Filtration project and associated pipeline located near SE Dodge Park Boulevard and SE Carpenter Lane in Gresham, Oregon known as the Property (see Figure 1A attached). It should be noted that True North is not the geotechnical or environmental consultant of record for the project. True North is providing Cottrell CPO with commentary on available documents relating to the proposed PWB Water Filtration project.

Proposed development of the 95-acre Property will consist of the following:

- Filtration Facility administrative office building (2-story), equipment and chemical storage buildings (1 to 2-story), utilitarian process structures (1-story), water reservoirs, septic systems and associated driveways and parking lots.
- Communication Tower 180-foot-tall Communication tower located in northeast corner.

In addition, 2-miles of new pipelines will be constructed to and from the filtration facility (see Figure 1B attached). Pipelines will consist of the following:

- Raw Water (i.e., unfiltered) pipelines along SE Dodge Park Boulevard, SE Lusted Road with trenchless crossings (tunneling) under SE Dodge Park and SE Proctor Road.
- Finished/Treated Water (i.e., filtered/treated) pipelines along SE Dodge Park Boulevard, SE Lusted Road and SE Altman Road.

True North was able to review documents provided by you and documents available through the County, City and State of Oregon Department of Geology and Mineral Industries (DOGAMI) and Oregon State Water Resources Department (OWRD). The majority of documents related to the proposed development were found on the Multnomah County Document Library for the Portland Water Bureau (PWB) Treatment Plant (<a href="https://www.multco.us/landuse/document-library-pwb-treatment-plant">https://www.multco.us/landuse/document-library-pwb-treatment-plant</a>). Documents to the PWB website were consistently uploaded/removed and therefore <a href="not all documents are presumed to have been uploaded or reviewed. Items listed below may have been addressed in documents not available for review at this time.

Of the documents that we were able to review, the following items were noted that may need further analysis:

<u>Water Wells</u> – True North was able to locate at least 2 monitoring wells, used for observing groundwater levels, flow condition, etc., on the Property during our site walk on June 21, 2023. Based on OWRD records, it appears a minimum of 170 water/monitoring wells are located within a mile radius of the Property from SE Lusted Road to SE Proctor Road (see Figure 2 attached). Details on water wells may have been addressed in documents not available for our review at this time. However, we recommend further study, including mapping, of existing irrigation and domestic wells to determine if water/monitoring wells are located within areas of proposed construction of the facility and/or pipelines or could be negatively impacted by future construction/operations on the Property. If there are wells situated within construction areas, they will need to be abandoned/decommissioned or replaced by a licensed well driller per Chapter 690 of State of Oregon Water Resource guidelines. If there are domestic or irrigation wells which could be impacted, we recommend further study to preserve existing water production, quality, and rights. Also see comments in the Tunneling section within this memorandum.

<u>Expansive Soil</u> – Approximately 20-feet of "fat clay", defined as cohesive and compressible in nature with high plasticity and a liquid limit of 50 or greater, was observed by others on the Property. It is undetermined if expansion soil index testing was conducted on the fat clay to determine shrink-swell potential. <u>Details on expansive soils may have been addressed in documents not available for our review at this time</u>. However, we recommend further testing be conducted to determine if expansive soils exist on the Property and/or within areas of pipeline construction. If expansive soils are found, additional design modifications may be needed.

Stormwater – True North engaged Dennis Caudell, PE (with Paradise Environmental, who is a consultant with experience with stormwater permitting, design and compliance). Caudell commented the Finished Water Intertie Stormwater Drainage Report makes a passing reference to Beaver Creek's status of having existing Total Maximum Daily Load (TMDL) and 303(d) listing for impairments that include persistent organic pesticides and chlorinated compounds. At a minimum, the stormwater management report should include an analysis of the potential for mobilization of these constituents (particularly if left exposed at the ground surface during or after construction), and the resulting management required of not only construction activities, but also the protection of Beaver and Johnson Creeks during the facility implementation as well as its ongoing operation. The report should call out specific best management practices to ensure that agricultural runoff, documented within the Phase 1 and Phase 2 Environmental Site Assessments conducted by others, does not become facility run-on and a resulting contaminated discharge to an already quality limited Beaver and Johnson Creeks.


Septic – On site septic systems are proposed for the Property. <u>Details on septic design may have been addressed in documents not available for our review at this time</u>. However, with steep slopes and associated Geologic Hazard Overlay (GHO) zones situated approximately 60 feet northeast of a proposed drain field on the Property, we recommend further evaluation be conducted to confirm drainage will not discharge into the GHO.


Tunneling — Large diameter pipelines will be located at depth below overlay zones mapped adjacent to the Property. There is the potential existing irrigation/domestic wells, which have an average depth of 200 to 300 feet below ground surface (bgs), may be impacted by tunneling methods. As detailed on Figure 2, a cluster of irrigation/domestic wells are mapped by OWRD as being within the proposed tunneling area located below SE Dodge Park. Groundwater levels are anticipated to be near 150-feet bgs. Tunneling activity in water-bearing ground may result in unwanted groundwater inflow into the excavated area, causing some groundwater drawdown within nearby wells. Details on tunneling may have been addressed in documents not available for our review at this time. However, we recommend mapping and detailed research of existing irrigation and domestic wells to determine if they are located within the proposed tunneling area or could be impacted by future construction and/or operations on the Property. In addition, we recommend groundwater control systems and prevention of groundwater intrusion be factored into the design of proposed tunneling.

Attachments: Figure 1A – Proposed Development (Filtration Facility)

Figure 1B – Proposed Development (Pipelines)


Figure 2 – Well Locations (approximate – without address or ground truthing)





SOURCE: FIGURE ES-7 DRAWING PREPARED BY BROWN AND CALDWELL & ASSOCIATED FIRMS, DATE CREATED 10/2020.

TRUE NORTH  • GEOTECHNICAL •	Cottrell CPO Portland Water Bureau Water Filtration Facility Gresham, OR	Project # 23-0108-1
219 West 4 <sup>th</sup> St Vancouver, WA 98660 360-984-6584	June 2023	Figure 1B – Proposed Development (Pipeline)



**CLAC 938 CLAC 911** MULT 57354 MULT 137834 **CLAC 921** MULT 131614 MULT 134517 **CLAC 937 CLAC 20244 CLAC 916** MULT 130681 CLAC 52510 CLAC 65950 MULT 123249 **CLAC 895 CLAC 915 CLAC 904** MULT 129630 **CLAC 898** CLAC 75739 MULT 131422 **CLAC 934 MULT 2594** MULT 133087 MULT 134511 MULT 106475 MULT 102716 **CLAC 70770 CLAC 932** MULT 131494 MULT 131963 CLAC 74945 CLAC 55367 **CLAC 8999** MULT 65190 CLAC 54463 MULT 138851 **CLAC 918** CLAC 50350 MULT 138043 CLAC 76773 **CLAC 940 CLAC 923** MULT 137745

Wells within 1-mile radius of Property:

MULT 134521 **MULT 2600** MULT 137835 **CLAC 901** CLAC 19433 MULT 138791 **CLAC 900** CLAC 60384 CLAC 20550 CLAC 75740 MULT 133088 MULT 60890 MULT 137832 MULT 131615 MULT 102715 MULT 106476 CLAC 74946 MULT 106470 **CLAC 917** MULT 56024 MULT 134518 **CLAC 920** 

**CLAC 75330 CLAC 914 CLAC 902 CLAC 931** CLAC 64497 **CLAC 908** MULT 102412 MULT 131424 CLAC 57578 **CLAC 894 MULT 2586** CLAC 58931 **CLAC 919** CLAC 50160 MULT 106473 CLAC 50962 MULT 131964 MULT 131423 **CLAC 959 MULT 2598** MULT 137833 CLAC 51409

360-984-6584

**CLAC 922 CLAC 20547 CLAC 75505** CLAC 54551 MULT 131425 MULT 106474 **MULT 2592** MULT 131495 MULT 134778 **CLAC 62309** MULT 133086 MULT 129631 MULT 133539 **CLAC 942 CLAC 907** CLAC 56617 MULT 137746 CLAC 52790 **MULT 2601 CLAC 910 CLAC 905** MULT 102410

MULT 138792 MULT 137690 MULT 130682 CLAC 59522 MULT 137689 MULT 102411 MULT 104020 **CLAC 19898** MULT 119026 **CLAC 913** MULT 131492 MULT 104021 CLAC 62091 **CLAC 896** MULT 136942 **MULT 2590 CLAC 929** MULT 129629 MULT 106471 **CLAC 1479 MULT 2595 CLAC 53033** MULT 134510 MULT 106472 MULT 131616 CLAC 58255 **CLAC 928 MULT 2596** MULT 131962 MULT 131493 **CLAC 939** MULT 102718 MULT 102717 **CLAC 906 CLAC 935** MULT 134520 MULT 134519 MULT 137836 **CLAC 924 MULT 2599 CLAC 909 CLAC 961 CLAC 912** CLAC 12302

MULT 130680
CLAC 941
MULT 2593
CLAC 943
CLAC 74947
CLAC 18417
MULT 94299
MULT 139200
MULT 44
MULT 106469
CLAC 946
CLAC 75661
MULT 102719
CLAC 77409
CLAC 930

CLAC 20552

SOURCE: OREGON WATER RESOURCES DEPARTMENT, DATE ACCESSED/CREATED 6/2/2023.

SCALE: 1INCH = 1,000 FT

TRUE NORTH  • GEOTECHNICAL •	Cottrell CPO Portland Water Bureau Water Filtration Facility Gresham, OR	Project # 23-0108-1
219 West 4 <sup>th</sup> St Vancouver, WA 98660	June 2023	Figure 2 – Well Locations



# PWB Treatment Plant - T3-2022-16220 Comments

1 message

# tima@tnorthgeo.com <tima@tnorthgeo.com>

Thu, Jun 29, 2023 at 9:29 AM

To: LUP-Comments@multco.us

Cc: Paul Willis <willisteam@msn.com>, david@tnorthgeo.com, lauren.courter@gmail.com



External Sender - Be Suspicious of Attachments, Links, and Requests for Payment or Login Information.

Please see attached memo/comments for the proposed PWB Water Facility at SE Dodge Park Blvd and SE Carpenter Lane in Gresham. If you have any questions, please let us know.

Thank you,

Tima Carlson, R.G.

**Project Geologist** 

**True North Geotechnical Services** 

http://www.tnorthgeo.com/

\*\*\*Please note that we have moved offices\*\*\*

New Address:

219 W. 4th Street

Vancouver, WA 98660

office: 360-984-6584

cell: 503-705-8014

7

23-0108 Cottrell CPO - PWB Water Facility Review Memo.pdf

2442K